




1




2





3




4





5




See mounting instructions for art
3-250-0 on next page.

3-250-0


1




2




3




4




5




6




7





6



7



WORKPLACES FOR INDUSTRIES



www.wfiab.se