



2x




4x



4x




1x




1x



1x



1x



1x



M10x30
8x




M8x20
12x



M8x16
8x



5x20
6x



M10x30
4x



M10-lock
8x



M8-lock
8x



M8
4x



Flatmutter M8
8x




10,5x20x2,0
16x




8,4x16x1,6
44x


1






2





3











5x20
6x



WORKPLACES FOR INDUSTRIES



www.wfiab.se