

M8x20
6x



6,0x16
6x



M6x12
8x




6,4x12x1,5
8x




M6
8x


1




2





3




4





5




See mounting instructions for art
3-250-0 on next page.

3-250-0


1




2




3




4




5




6




7






6




7

8




Handwritten mark




Handwritten mark


9



10



11





WORKPLACES FOR INDUSTRIES



www.wfiab.se